



Banjo 2" Poly Hydraulic Pump



Moorhead, MN 56560
218-236-1818
800-365-3070
www.riverbendind.com

[Click Here For Pump Breakdown](#)



For Hydraulic Assemblies Manufactured After January 25, 2002

REPLACEMENT PARTS 2" HYDRAULIC ADAPTER				
REF. NO	PART NO.	DESCRIPTION	QTY PER PUMP	
1	12049B	Hydraulic Pedestal Housing	1	
2	12055B	Adapter Shaft	1	
3	17056	Bearing	1	
4	V20018	$\frac{3}{8}$ " Lockwasher	2	
5	18010S S	$\frac{3}{8}$ " - 16 x1.25" HHCS	2	
6	HY101 3	Gresen Hydraulic Motor	1	
7	12600B	Complete Hydraulic Assembly	1	