



Banjo 220 Manifold Strainer



Moorhead, MN 56560
218-236-1818
800-365-3070
www.riverbendind.com



REPLACEMENT PARTS - MLS220

ITEM	PART NO.	DESCRIPTION	QTY
1	MLS220B	2" FP Manifold Strainer Body	1
2	MLS220C	2" FP Manifold Strainer Cap	1
3	MLS220R	2" FP Strainer Clamp	1
4	LSQ200-PL	Plug	1
5	LSQ200-R	O-Ring	1
6	MLS220G	2" FP EPDM Gasket	1
6	MLS220GV	2" FP FKM(viton type) Gasket	1
7	LST204SS	2" FP Strainer Screen 316 SS 4 Mesh	1
7	LST206SS	2" FP Strainer Screen 316 SS 4 Mesh	1
7	LST208SS	2" FP Strainer Screen 316 SS 8 Mesh	1
7	LST210SS	2" FP Strainer Screen 316 SS 4 Mesh	1
7	LST216SS	2" FP Strainer Screen 316 SS 4 Mesh	1
7	LST230SS	2" FP Strainer Screen 316 SS 4 Mesh	1
7	LST250SS	2" FP Strainer Screen 316 SS 4 Mesh	1
7	LST280SS	2" FP Strainer Screen 316 SS 4 Mesh	1
7	LST2100SS	2" FP Strainer Screen 316 SS 4 Mesh	1
8	MLS234G	Screen Gasket	1