




BANJO MANIFOLD STRAINERS MLS-300 and MLS222



Moorhead, MN 56560
218-236-1818
800-365-3070
www.riverbendind.com



REPLACEMENT PARTS MLS-300				
ITEM	PART NO	DESCRIPTION	QTY	
1	MLS300B	3" Manifold Strainer Body	1	
2	MLS300CAP	3" Strainer Cap	1	
3	LS300EC	End Cap	1	
4	LS300ECG	3" Strainer End Cap Gasket	1	
4	MLS300ECGV	3" Strainer End FKM (viton type) Cap Gasket	1	
5	13777	3" Strainer End Cap Plug	1	
6	13778	3" Strainer End Cap Plug Gasket	1	
7	MLS300G	3" Strainer Cap Gasket	1	
7	MLS300GV	3" Strainer FKM (viton type) Cap Gasket	1	
8	LS304	3" 4 Mesh Line Strainer Screen	1	
8	LS308	3" 8 Mesh Line Strainer Screen	1	
8	LS312	3" 12 Mesh Line Strainer Screen	1	
8	LS320	3" 20 Mesh Line Strainer Screen	1	
8	LS350	3" 50 Mesh Line Strainer Screen	1	

REPLACEMENT PARTS MLS-222				
ITEM	PART NO	DESCRIPTION	QTY	
1	LST204SS	316S S 4 Mesh Strainer Screen	1	
1	LST206SS	316S S 6 Mesh Strainer Screen	1	
1	LST208SS	316S S 8 Mesh Strainer Screen	1	
1	LST210SS	316SS 10 Mesh Strainer Screen	1	
1	LST216SS	316SS 16 Mesh Strainer Screen	1	
1	LST230SS	316SS 30 Mesh Strainer Screen	1	
1	LST250SS	316SS 50 Mesh Strainer Screen	1	
1	MLS250SS	316SS 50 Perforated Screen	1	
1	LST280SS	316SS 80 Mesh Strainer Screen	1	
1	MLS280SS	316SS 80 Perforated Screen	1	
1	LST2100SS	316SS 100 Mesh Strainer Screen	1	
2	MLS220B1	Strainer Body	1	
3	MLS220C1	Strainer Cap	1	
4	MLS220R1	Strainer Ring	1	
5	LSQ200R	Plug Gasket	1	
6	LSQ200PL	Plug	1	
7	MLS220G1	Body Gasket	1	
2-7	MLS220BC	Complete Strainer Less Screen	1	