


Moorhead, MN 56560
 218-236-1818
 800-365-3070
www.riverbendind.com



Seal and O-ring Repair Kit
 No. 3430-0347 consists of
 (2) Ref. 11 seals (Viton) and
 (1) Ref. 7 gasket.

Ref. No.	Qty. Req'd.	Part Number	Description
1	1	0150-9600C	Body
2	1	0250-9600C	Housing
3	1	1201-0015	Impeller Insert
4	1	0500-9600	Shaft, stainless steel, 15/16" diameter, 1/4" keyway
5	1	0400-9600P	Impeller, corrosion-resistant Valox®
6	1	1610-0045	Key - Woodruff

Ref. No.	Qty. Req'd.	Part Number	Description
7	1	1710-0015	Gasket
8	3	1810-0008	Retainer ring - external
9	1	1820-0025	Retainer ring - internal
10	2	2008-0001	Sealed ball bearing
11	2	2112-0003	Seal - Viton
12	1	2300-0020	Bearing cover
13	6	2210-0026	Screw, hex head
14	1	2406-0007	Pipe plug
15	1	6031-0299	Decal